

Case study: polishing of OEM clearcoats

Situation:

30% of the bodies in a car factory are coated with a scratch resistant clearcoat. 70% of the bodies are coated with traditional clearcoats.

Effect:


The amount of time needed for spot repair on bodies with scratch resistant coatings is up to 100% above standard.

Problem:

Paint defects cannot be eliminated properly without interrupting the flow of production.

Solution:

By using a polish especially formulated for this application paint defect on scratch resistant coatings could be eliminated within the standard time.



Standard time

